

# Gardner Denver Nash Fiberscope Inspections



Rotor blades - worn and new - as viewed by a fiberscope

## A Fiberscope Inspection:

- State-of-the-art digital videoscope technology for internal examination of the pump
- Provides a written report of internal and external conditions with pictures
- Inspects the pumps in place without disassembly
- Determines if the pump is the problem
- Can determine cause of failure
- Provides an accurate repair quote based on inspection
- Helps you plan your maintenance budget
- Show you which pumps should be repaired first, to achieve the best return in production



If you have any further questions or would like more information, please contact the service center at right.

**Gardner Denver Nash  
Service Center - Birmingham**  
Ray Golden  
1851 Floyd Bradford Road  
Birmingham, AL 35173  
phone: +1 205 951 2721 x802  
fax: +1 205 951 2724  
ray.golden@gardnerdenver.com  
GardnerDenverNash.com

**Gardner Denver  
Engineered Products Div.**  
9 Trefoil Drive  
Trumbull, CT 06611 USA  
phone: 1 800 553 NASH  
+1 203 459 3900  
fax: +1 203 459 3988  
nash@gardnerdenver.com  
GardnerDenverNash.com